

Prepared (Subject resp)		No.	
jjdmawan Marshall Wang		FPM-ext-2023:53	
Approved (Document resp)	Checked	Date	Rev
jiddxiea David Xie		6/12/2023	A

Product Discontinuation Notice - End of life PIM4328P & PIM4x06SD products

For Your Information

Receiver

Sales and FAE world-wide

All of Customers

Product Discontinuation Notice - End of life PIM4328P & PIM4x06SD products

Flex Power Modules has taken a decision to discontinue the following products in PIM (Power Interface Module) series:

Affected products

- PIM4328P** 10-12 A / 3.3 V, 3.6 A / 5 V, 0.15 A;



PIM4328P analog version quarter brick power interface module

Size: 57.9 x 36.8 x 10.7 mm (2.28 x 1.45 x 0.42 in.)

More information about PIM4328P product, please see

[fpm-techspec-pim4328 \(flexpowermodules.com\)](http://fpm-techspec-pim4328.flexpowermodules.com)

2. PIM4x06SD series

PIM4106SD 2.56A/100W

PIM4206SD 5.12A/200W

Prepared (Subject resp) jdmawan Marshall Wang		No. FPM-ext-2023:53	
Approved (Document resp) jiddxiea David Xie	Checked	Date 6/12/2023	Rev A

PIM4306SD 7.69A/300W
PIM4406SD 10.3A/400W



PIM4x06SD series power interface module

Size: 33.02 x 22.86 x 7 mm (1.30 x 0.9 x 0.28) inch.

More information about PIM4x06 products, please see

[fpm-techspec-pim4006 \(flexpowermodules.com\)](http://fpm-techspec-pim4006.flexpowermodules.com)

Date for last time order

The last date for placing orders on affected products will be **Jun 15th, 2024** and the last date for delivery will be **Jun 15th, 2025**.

Recommendation for replacement candidate

The recommended replacements for above discontinued products are listed in below table,

Product to be EOL	Footprint	Iout (A)	Recommended Replacement	Footprint	Iout (A)
PIM4328P, Analog version	Quarter brick	10 A	PIM4328PD or PIM4328PDA, With I2C or PMBus interface	Quarter brick	12 A
PIM4x06SD	Sixteenth Brick	2.56 A-10 A	PIM4328PD or PIM4328PDA, With I2C or PMBus interface	Quarter brick	12 A



Prepared (Subject resp)	No.		
jidmawan Marshall Wang	FPM-ext-2023:53		
Approved (Document resp)	Checked	Date	Rev
jiddxiea David Xie		6/12/2023	A

For more information about recommended replacement product PIM4328PD or PIM4328PDA, please refer to

<https://flexpowermodules.com/resources/fpm-techspec-pim4328>

The recommended replacement is depending on the actual application and its specific requirements, for more details, please consult your local Flex Power Modules representative for advice.

If you have any questions, please do not hesitate to contact the undersigned.

Best regards,

Marshall Wang
Product Manager

Flex Power Modules
Phone: +86 21 5990 3258-26135
Email: Marshall Wang Marshall.Wang@flex.com